# Fixture-Fix, LLC

PO Box 104, Oyster Bay, New York 11771-0104, USA - Phone - 718-349-8873 - FAX- 718-349-8873

### ALL PRODUCTS MANUFACTURED IN THE U.S.A.

### MATERIAL SAFETY DATA SHEET

### Porc-a-Fix

EMERGENCY INFORMATION TELEPHONE NUMBER: 718-349-8873

DATE OF PREPARATION: 05/01/2013

#### SECTION I - PRODUCT IDENTIFICATION

PRODUCT NUMBER: 0056

National Fire Protection Association

PRODUCT NAME: PORC-a-FIX Porcelain Touch-Up Glaze

Health - 2

PRODUCT CLASS: Vinyl Toluene Alkyd

Flammability - 3 Reactivity - 0

### **SECTION II - HAZARDOUS INGREDIENTS**

PERCENT

OCCUPATIONAL

**EXPOSURE LIMITS** 

VAPOR PRESSURE

**INGREDIENT** 

TLV PEL

VMP Naphtha (Aliphatic Hydrocarbon)

CAS #64742-89-8

300 ppm

2mm Hg at 20

Mineral Spirits (Aliphatic Hydrocarbon)

CAS #64742-47-8

100 ppm 2.9mm Hg at 20

### SECTION III - PHYSICAL DATA

BOILING RANGE: 250-388 F

VAPOR DENSITY: HEAVIER THAN AIR

65.3% VOLATILE VOLUME WT/G 8.2

EVAPORATION RATE: SLOWER THAN ETHER

## SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION: OSHA: 1B FLASH POINT: 50 F EXTINGUISHING MEDIA: FOAM, CO2, DRY CHEMICAL

LEL: 1.0

DOT: Flammable

UNUSUAL FIRE AND EXPLOSION HAZARDS - Isolate from heat, electrical equipment, sparks and open flame. Closed containers may expose when exposed to extreme heat. During emergency condition, overexposure to combustion products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention. Vapors may be ignited by static electricity or sparks.

SPECIAL FIREFIGHTING PROCEDURES - Full protective equipment, including self contained breathing apparatus, should be used to protect firefighters from any hazardous combustion products.

## SECTION V - HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE - Inhalation: Anesthetic. Irritation of the respiratory tract or acute nervous system depression characterized by: Headache, dizziness, staggering gait, confusion, unconsciousness or coma. Skin or eye contact: Primary irritant

MEDICAL CONDITIONS PRONE TO AGGRAVATION BY EXPOSURE: None known.

PRIMARY ROUTE(S) OF ENTRY: DERMAL, INHALATION

EMERGANCY AND FIRST AID PROCEDURES - Inhalation: Remove to fresh air. Restore breathing. Treat symptomatically. Consult physician. Splash (eyes): Flush immediately with large amounts or water - see physician. Splash (skin): Wash affected areas with soap and water. Remove contaminated clothing. Consult physician if irritation persists. Ingestion: Drink 1 or 2 glasses of water to dilute. Do NOT induce vomiting. Consult physician - treat symptomatically.

### PORC-a-FIX MATERIAL SAFETY DATA SHEET

PAGE 2

11-1201 11-1211 11-1200 11-1213 11-1202 11-1203 11-1215 11-1204 11-1205

#### SECTION VI - REACTIVITY DATA

STABILITY: STABLE

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

HAZARDOUS DECOMPOSITION - Products may produce fumes when heated to decomposition as in welding or fire. Fumes may contain: carbon monoxide, carbon dioxide, oxides of nitrogen and other products of combustion.

CONDITIONS TO AVOID: Heat, sparks or open flame.

INCOMPATIBILITY (MATERIALS TO AVOID): None reasonably foreseeable.

### SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED - Limit spread of spill or leak. Remove all sources of ignition. Soak up with inert absorbent material. See Section VIII for required protective measures. Keep material out of sewers and/or drains.

WASTE DISPOSAL METHOD: Dispose of in accordance with all local, state and federal regulations. Approved land fill: approved hazardous waste site, or incineration.

### SECTION VIII - SAFE HANDLING AND USE INFORMATION

RESPIRATORY PROTECTION - If TLV or PEL of product or any component is exceeded; a NIOSH MSHA approved air supplied respirator is advised.

VENTILATION - Ventilation of sufficient volume and pattern should be provided to keep air contaminant concentrations below values in Section II.

PROTECTIVE GLOVES - Required, rubber or neoprene to prevent skin contact.

EYE PROTECTION - Use safety eyewear including splash guards or side shields.

OTHER PROTECTIVE EQUIPMENT - Wear chemical resistant shoes. Remove and wash contaminated clothing before re-use. HYGIENIC PRACTICES - Wash hands before eating or using the washroom. Smoke in smoking areas only.

### SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING - Store away from extreme heat, fire, or open flame. Store in accordance with OSHA 1910.106. Store in well ventilated areas.

OTHER PRECAUTIONS - Do not take internally. Avoid repeated or prolonged contact with skin. Do not store near heat, sparks, or open flame. Drums of this material should be grounded and bonded when pouring. Containers must not be washed out or used for other purposes.